

Attorney Docket No. 1614.1382

## IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

ATTENTION

In re Patent Application of:

Haruo KOIZUMI, et al.

Application No.: 10/768,066

Confirmation No.: 6125 CERTIFICATE OF CORRECTION

Filed: February 2, 2004 BRANCH

U.S. Patent No.: 7,061,361

Issued: June 13, 2006

For: CIRCUIT BOARD ASSEMBLY AND FLAT COIL

## REQUEST FOR CERTIFICATE OF CORRECTION

Commissioner for Patents PO Box 1450 Alexandria, VA 22313-1450

Certificate

NOV 2 8 2006

Sir:

Patentee(s) respectfully request(s) that a Certificate of Correction be issued in the subject patent, pursuant to 35 USC § 254 and 37 CFR § 1.322, to correct the error(s) shown on the attached Form PTO-1050. A check in the amount of \$100 to cover the cost of the Certificate is attached.

One or more of the errors shown on the attached Form PTO-1050 is or are within the responsibility of the applicant; each thereof is of a clerical or typographical nature or of minor character and occurred in good faith, and the correction thereof is consistent with the prosecution record.

Respectfully submitted,

STAAS & HALSEY LLP

rov. 20, 2006

Registration No. 22,010

1201 New York Ave, N.W., 7th Floor

Washington, D.C. 20005 Telephone: (202) 434-1500 Facsimile: (202) 434-1501

Milluz 00000072 7061361

Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number. (Also Form PTO-1050)

## UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO: 7,061,361 DATED: June 13, 2006

INVENTOR(S): Haruo KOIZUMI, et al.

It is certified that error appears in the above-identified patent and that said Letters Patent are hereby corrected as shown below:

Column 10, Line 22, after "substrate" insert --,--.

MAILING ADDRESS OF SENDER: STAAS & HALSEY 1201 New York Avenue, N.W. 7th Floor Washington, DC 20005

PATENT NO. <u>7,061,361</u>

No. of add'l copies @ 304 per page